


GM All Lights On



Spade Terminal:

- The spade terminal is supplied to allow the activation of an accessory relay using the high-beam switch. The spade terminal will provide a signal ground to activate a relay when the high-beams are turned on.
- To use, solder the spade's prongs in the holes between the diodes.

WARNING: The spade terminal signal ground is NOT intended to provide a high amperage ground. It is only rated for a signal ground that will control a relay.

Installation Instructions:

1. Remove the relays labeled: FOG LP, HDLP-LOW, DRL, HDLP-HI
2. Lay the GM All Lights On circuit board in the location shown below
3. Reinstall the relays back into their original location

